8 June 1971

### FLOOR & RAILS

1. New Rails or Bring Concrete to Top of Rail

The same of the same

- 2. Level & Straighten the Concrete
- 3. Tile isn't Setting Tight
- 4. Concrete ran through the First Floor
- 5. Center Aisle will have to be Covered after Bays are Finished
- 6. Should Concrete be Poured under Stationary Shelves? If it is, do we need the Plywood Deck under the Bottom Shelf?
- 7. Cut out Wooden Deck for the Chain Return Box
- 8. Concrete not Bonded to the old Floor. Why? Should it be?
- 9. Where are the wheels for the carts and what size are they? Will they work?

#### SHELVES

# 25X1A9a

- 1. The fourth brace on each upright angle has been put back on per Mr.
- 2. Shelves have been straightened, tightened and squared.
- 3. Brace that holds the electrical wire between shelves tends to droop and will hit top boxes.

## Approved For Release 2001/07/17 : CIA-RDP74-00005R000400080038-5

- 4. Shouldn't wire run closer to upright angle where it runs from top of shelves to chain pick up.
- 5. If metal is taken off the end shelves, couldn't a "hand" or box hit the electrical hook-up?
- 6. Couldn't the motor and control panel and other motor in each bay set under a fifteen in shelf? (Put a board in front of motor that could be removed.
- 7. The wire between first two motors was too short to let you take out a motor without disconnecting the wire. A new set of motors was put in. Can the motors be easily changed -- screw changed so that screw head pointed out.
- 8. How does safety alert wire hook to end panel?
- 9. Should be cleaned by washing in probably two (2) waters. Some arrangement should be made to keep shelves clean after completion of each bay.
- 10. How is the wire that runs on top of each row fastened down and where?
- ll. The safety will be put on the second bracket or angle from the floor. Need second nut on turnbuckle.

### LIGHTS

- 1. Small ducts will get one row of lights on angle.
- 2. Large ducts will get row of lights on each side at a angle.
- 3. Oversize will get probably a spotlight.

#### 25X1A6a

## ENGINEERS

Should the light fixtures that are taken out of building be kept on lower parking lot for the duration of the project? (70 so far)

Approved For Release 2001/07/17: CIA-RDP74-00005R000100080038-5